

**Highway Authority: Telford & Wrekin
Site & Location Summary 2016**

Site: 22-3CA878 - Station Road Ketley Class & Status: Core - Operational - Approved: 04-Apr-05
Grid References Start: 367160 - 310965 End: 368160 - 311066

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3CA878	367397	311055	Operational	Gatsometer BV Type 24+AUS - One Way	30
Surveys	365549	311430	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
1990							
1991	1	3	1	7			
1992	0	6	0	8			
1993	1	7	3	13			
1994	1	6	1	6			
1995	1	2	1	3			
1996	0	2	0	3			
1997	0	6	0	10			
1998	2	3	2	5			
1999	0	3	1	4			
2000	1	4	1	8			
2001	3	4	3	7			
2002	0	4	0	5			
2003	0	1	0	1		36	49
2004	0	3	0	4			
2005	0	3	0	4			
2006	1	3	1	3	23	26	2
2007	0	1	0	1			
2008	1	0	2	1			
2009	0	2	0	2			
2010	0	1	0	1			
2011	1	0	2	1	24.7	29.5	4.5
2012	0	2	0	3			
2013	0	1	0	1	24.7	33.1	22.9
2014	0	1	0	1			
2015	0	2	0	2	29.5	34.6	34
2016					29.2	34.7	34.8

Site: 22-3CA879 - King Street **Class & Status: Core - Operational - Approved: 02-Jun-05**
Grid References **Start: 365300 - 311277** **End: 365362 - 311728**

Location ID	Eastings	Northing	Location Status	Camera Model & Direction	Limit
3CA879	365549	311430	Operational	Gatsometer BV Type 24+AUS - One Way	30
3CA880	365546	311459	Operational	Gatsometer BV Type 24+AUS - One Way	30
Surveys	365983	310928	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
1990							
1991	2	2	2	2			
1992	0	1	0	3			
1993	0	1	0	1			
1994	0	1	0	1			
1995	0	2	0	2			
1996	2	6	2	10			
1997	0	3	0	9			
1998	0	1	0	1			
1999	0	2	0	2			
2000	2	0	2	0			
2001	1	2	1	4			
2002	0	1	0	1			
2003	0	2	0	2		33	32
2004	0	0	0	0			
2005	0	0	0	0			
2006	0	0	0	0	24	28	4
2007	0	2	0	2			
2008	0	1	0	1			
2009	0	1	0	1			
2010	0	2	0	2			
2011	1	2	1	3	20.8	28	1
2012	0	3	0	3			
2013	1	1	2	1	23	28	2.5
2014	0	0	0	0			
2015	1	3	1	3	23.5	28.3	1.9
2016					24.4	29.5	5.2

Site: 22-3CB863 - A442 Storchley **Class & Status: Core - Operational - Approved: 01-Jun-12**
Grid References **Start: 371013 - 303751** **End: 371316 - 308154**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3CB863	371137	306290	Operational	Teletraffic Concept DVD system - One Way	60
3CB864	371216	306453	Operational	Teletraffic Concept DVD system - One Way	60
Surveys	371184	308132	Operational	N/A - N/A	60

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over PSL
	KSI	PIC	KSI	PICS			
2005	1	18	1	20			
2006	2	4	2	7			
2007	2	9	2	12			
2008	3	9	3	9			
2009	3	7	3	9			
2010	1	9	1	14			
2011	0	4	0	5			
2012	0	3	0	4	52.2	60.2	-
2013	0	1	0	1			
2014	0	1	0	1	54.1	60.3	11.8
2015	0	0	0	0	54.5	60.8	14.1
2016					58.6	65.3	32.2

Site: 22-3CB836 - Haybridge Road **Class & Status: Core - Operational - Approved: 27-Feb-14**
Grid References **Start: 366552 - 311568** **End: 367574 - 312175**

Location ID	Eastings	Northing	Location Status	Camera Model & Direction	Limit
3CB836	366949	311811	Operational	Teletraffic Concept DVD system - Bi Directional	30
3CB837	366950	311812	Operational	Teletraffic Concept DVD system - Bi Directional	30
3CA885	366710	311698	Operational	Gatsometer BV Type 24+AUS - One Way	30
Survey	366685	311669	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	1	4	1	4			
2006	1	7	1	9			
2007	0	7	0	9			
2008	0	2	0	6			
2009	1	1	1	3			
2010	1	1	1	1			
2011	0	7	0	10			
2012	0	3	0	3			
2013	1	2	1	3	34.9	38.5	37.8
2014	0	4	0	8			
2015	0	2	0	3	27.5	31.1	15.3
2016							

Site: 22-3DB306 - Randlay Avenue **Class & Status: Exceptional - Operational - Approved: 27-Feb-14**
Grid References **Start: 370370 - 306990** **End: 371030 - 307900**

Location ID	Eastings	Northing	Location Status	Camera Model & Direction	Limit
3DB306	370388	307632	Operational	Teletraffic Concept DVD system - Bi Directional	30
Surveys	370393	307316	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	2	0	2	0			
2006	0	2	0	4			
2007	0	4	0	5			
2008	1	0	1	0			
2009	0	3	0	5			
2010	0	1	0	1			
2011	0	1	0	1			
2012	1	1	1	3			
2013	2	3	2	5			
2014	0	2	0	2			
2015	0	0	0	0	30.8	36.8	50
2016					31.7	38	57.3

Site: 22-3CA881 - Dawley Road Class & Status: Core - Operational - Approved:12-Dec-2005
 Grid References Start: 365901 - 310507 End: 366210 - 311055

Location ID	Eastings	Northing	Location Status	Camera Model & Direction	Limit
3CA881	365983	310928	Operational	Gatsometer BV Type 24+Aus	30
3CA882	366125	310632	Suspend	Gatsometer BV Type 24+Aus	40
Surveys	366736	312422	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
1990							
1991	0	1	0	1			
1992	0	2	0	2			
1993	3	1	3	1			
1994	0	0	0	0			
1995	0	3	0	3			
1996	1	3	1	3			
1997	2	1	1	6			
1998	0	3	0	3			
1999	2	1	2	1			
2000	0	0	0	0			
2001	0	1	0	3			
2002	1	1	1	1			
2003	0	3	0	5			
2004	1	5	1	5			
2005	2	1	2	2			
2006	0	1	0	1			
2007	0	2	0	2			
2008	0	2	0	2			
2009	0	0	0	0			
2010	0	1	0	1			
2011	0	1	0	3	22	28.6	0.9
2012	0	2	0	5			
2013	0	2	0	2			
2014	0	1	0	1			
2015	0	1	0	1			
2016					22.3	26.3	1.4

Site: 22-3CA883 - Leegate Avenue Class & Status: Core - Operational - Approved:09-Dec-2005
 Grid References Start: 366406 - 312061 End: 3667205 - 313424

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3CA883	366736	312422	Operational	Gatsometer BV Type 24+Aus	30
3CA884	366499	312568	Operational	Gatsometer BV Type 24+Aus	30
Surveys	363141	318285	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
1990				0			
1991	0	0	0	0			
1992	0	0	0	0			
1993	0	0	0	1			
1994	1	0	1	4			
1995	2	5	3	8			
1996	1	5	2	6			
1997	1	4	2	4			
1998	1	5	1	7			
1999	1	4	2	7			
2000	0	3	0	3			
2001	0	4	0	4			
2002	0	0	0	0			
2003	0	1	0	2			
2004	2	1	3	3			
2005	0	4	0	5			
2006	0	1	0	2			
2007	0	0	0	0			
2008	0	0	0	0			
2009	1	0	1	0			
2010	0	3	0	3			
2011	0	2	0	2	25.8	29.8	3.9
2012	0	0	0	0			
2013	0	2	0	3			
2014	0	1	0	2			
2015	1	1	1	4			
2016					26.6	30.1	5

Site: 22-3DB307 - Colliers Way **Class & Status: Core - Operational - Approved: 18-Feb-2015**
Grid References Start: 368438 - 309037 End: 369274 - 309509

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB307	368580	309480	Operational	Teletraffic Concept DVD system - Bi Directional	30
3DB308	368580	309480	Operational	Teletraffic Concept DVD system - Bi Directional	30
Surveys	368591	307477	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	2	0	2			
2006	0	0	0	0			
2007	0	0	0	0			
2008	0	1	0	1			
2009	1	0	1	0			
2010	0	0	0	0			
2011	0	2	0	2			
2012	0	1	0	1			
2013	0	0	0	0			
2014	0	1	0	2	31.5	36.9	59.6
2015	0	2	0	4	32	38.1	63.3
2016					30.7	35.8	51.3

Site: 22-3CB309 - Bridgnorth Road **Class & Status: Core - Operational - Approved: 18-Feb-2015**
Grid References Start: 370480 - 303804 End: 370689 - 304658

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB309	370684	303867	Suspended	Teletraffic Concept DVD system - Bi Directional	30
3DB323	370687	303802	Operational	Teletraffic Concept DVD system - Bi Directional	30
Surveys	370679	304192	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	0	0	1			
2006	0	1	0	1			
2007	0	1	0	0			
2008	0	0	0	0			
2009	0	0	0	0			
2010	0	1	0	2			
2011	0	1	0	1			
2012	0	1	0	2			
2013	0	0	0	0			
2014	0	0	0	0	32.5	38	62.3
2015	0	1	0	0			
2016					32.8	38.8	66.2

Site: 22-3CB310 - Legges Way Madeley Class & Status: Core - Operational - Approved: 10-Aug-15

Grid References Start: 369384 - 303545 End: 370070 - 304467

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3CB310	369552	303713	Operational	Teletraffic Concept - Bi	30
3CB318	369790	303948	Operational	Teletraffic Concept - Bi	30
Survey	369788	303931	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	1	0	1			
2006	1	1	1	1			
2007	0	1	0	1			
2008	1	1	1	1			
2009	0	1	0	1			
2010	1	1	1	1			
2011	0	2	0	2			
2012	0	4	0	6			
2013	0	1	0	1			
2014	2	3	2	4	36	41	82.9
2015	0	1	0	1			
2016					36.7	44.8	75.5

Site: 22-3DB311 - Dale Road Class & Status: Exceptional - Operational - Approved: 10-Aug-15

Grid References Start: 366632 - 303747 End: 366992 - 304339

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB311	366846	304104	Operational	Teletraffic Concept - Bi	30
3DB312	366846	304104	Operational	Teletraffic Concept - Bi	30
Survey	366836	304085	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	0	0	0			
2006	0	0	0	0			
2007	0	0	0	0			
2008	0	1	0	2			
2009	0	0	0	0			
2010	0	0	0	0			
2011	1	0	2	0			
2012	0	1	0	1			
2013	0	0	0	0			
2014	0	1	0	2			
2015	0	0	0	0	31	35.9	47.4
2016					31.7	37.2	54.6

Site: 22-3DB313 - Dale Acre Way				Class & Status: Exceptional - Operational - Approved: 10-Aug-15	
Grid References		Start: 370178 - 308268		End: 370888 - 308929	
Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB313	370886	308498	Operational	Teletraffic Concept - Bi	30
3DB314	370670	308433	Operational	Teletraffic Concept - Bi	30
Survey	370441	308424	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	4	0	4			
2006	0	1	0	2			
2007	0	1	0	1			
2008	0	1	0	1			
2009	0	4	0	5			
2010	0	2	0	3			
2011	0	3	0	3			
2012	0	0	0	0			
2013	0	0	0	0			
2014	0	2	0	2			
2015	0	0	0	0	31.2	36.5	49.9
2016					30	35.2	40.3

Site: 22-3DB873 - B5062 Roden				Class & Status: Exceptional - Operational - Approved: 12-Aug-15	
Grid References		Start: 356977 - 316510		End: 357962 - 316610	
Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB873	357468	316577	Operational	Teletraffic Concept - Bi	30
Survey	357611	316585	Operational	N/A - N/A	30

Year	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
	KSI	PIC	KSI	PICS			
2005	0	0	0	0			
2006	0	0	0	0			
2007	0	0	0	0			
2008	0	0	0	0			
2009	0	0	0	0			
2010	0	0	0	0			
2011	0	0	0	0			
2012	0	0	0	0			
2013	0	0	0	0			
2014	0	0	0	0			
2015	0	0	0	0	34.9	41.6	74.9
2016					34	40.5	70.8

Site: 22-3DB320 - Waterloo Street Ironbridge Class & Status: Exceptional - Operational - Approved: 02 Jun 16

Grid References		Start: 367417 - 303243		End: 368125 - 303439	
Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
3DB320	367757	303340	Operational	Teletraffic Concept - Bi	30
3DB321	367757	303340	Operational	Teletraffic Concept - Bi	30
Survey	367681	303364	NA	NA	30

	COLLISIONS		CASUALTIES		Average speed (mph)	85th percentile (mph)	% over
2005	0	0	0	0			
2006	0	0	0	0			
2007	0	0	0	0			
2008	0	1	0	2			
2009	0	1	0	2			
2010	0	0	0	0			
2011	0	0	0	0			
2012	0	0	0	0			
2013	0	0	0	0			
2014	0	0	0	0			
2015	0	1	0	1	33.6	39.7	67.7
2016							